## Autodesk Fusion360 Leaflet

Export of an object as a stl. file

1. Open Menu via *File / 3D-Print*
2. Selection: chose your object
3. Format: STL (Binary)
4. Check refinement
   a. Low is almost never used
   b. Medium is recommended in most cases
   c. High can be useful for very detailed models, but generates large STL-files and may cause problems when loading in CURA
5. Deactivate *Send to 3D Print Utility*
6. Click *OK* to confirm
7. Save your file

Now continue with the software CURA to prepare the print.

Download Autodesk Fusion360:
https://www.autodesk.de/education/edu-software/overview?sorting=featured&filters=individual